

1/7




FIG. 1




FIG. 2

3/7

Operation of the
Optical Cross Connect




FIG. 3




FIG. 4A




FIG. 4B

FILED" 5940860

Docket No. RIC 97 036 D1

Appln No.: Not assigned

Title. Method and System for Restoring Coincident Line and Facility Failures

Inventors. Shoa-Kai Liu et al

Sheets of Drawings: 6 of 7

6/7

Second Failure - Module 3




FIG. 4C

Docket No.: RIC 97 036 D1

Appln No : Not assigned

Title Method and System for Restoring Coincident Line and Facility Failures

Inventors: Shoa-Kai Liu et al

Sheets of Drawings: 7 of 7

7/7




FIG. 5